

GWH BUILD - General Site Rules

- All persons working on this construction site will be formally inducted
- All leads and electrical equipment brought onto this site must be compliant with test and tagging requirements (3 monthly)
- Only trained and competent person to operate plant and machinery – Evidence of competency / tickets must be available at all times when working on a GWH Build site.
- Workers must be “*Safe Working at Heights*” trained to use safety harnesses. Safety Harnesses are to be inspected prior to each use
- All persons entering this site must have a General Induction Card and certificate of currency for workers compensation and public liability
- All Safe Work Method Statements (SWMS) must be provided for work on this site and work activities to be conducted in accordance with SWMS.
- All identified site hazards must be reported to the Site Manager or other company representative
- All mandatory and appropriate Personnel Protective Equipment (PPE) must be worn at all times on this site i.e. High visibility vests or shirts to be worn at all times on site **(no singlets allowed on site)**
- Any incident, near miss or potential hazard is to be reported to the Site Manager or other company representative as soon as possible
- All times whilst on site personnel must comply with GWH Build instructions / rules and or legislative requirements
- Use of PPE in hazardous conditions in accordance with SWMS
- Site speed limit on sites are 10km/h
- No trucks are to reverse without a spotter directing their movement
- Site is to be kept clean and materials stored in designated area/s
- Under no circumstance is scaffolding, temporary edge protection, and penetrations to be adjusted unless approved by GWH Build site management.
- Allowable loads on scaffolds will be identified on the “scaff tags” at scaffold entry points.
- No person is permitted to be under the influence of drugs and alcohol (ZERO TOLERANCE)
- Only **PLATFORM LADDERS** are to be used on site